



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION VI SITE NUMBER
OKD117545 764

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME Commander Finishing Company		B. STREET (or other identifier) 226 Adams Rd.	
C. CITY Sand Springs	D. STATE OK	E. ZIP CODE 74063	F. COUNTY NAME Tulsa
G. OWNER/OPERATOR (if known) 1. NAME Bill Wiles, Property Manager			2. TELEPHONE NUMBER (918) 584-3581 ext360

H. TYPE OF OWNERSHIP (if known)
☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☒ 5. PRIVATE ☐ 6. UNKNOWN

I. SITE DESCRIPTION

This site is upgradient of the Sand Springs N.P.L. Site. It is currently used for warehouse space, a woodworking shop, and a textile manufacturing firm. It was formerly a very large textile manufacturing firm. The site is several acres in size and composed of several large buildings and open areas.

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)

K. DATE IDENTIFIED
(mo., day, & yr.)

Request by US EPA Region VI to investigate sites upgradient of SS NPL site 5/2/88

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

Chlorinated hydrocarbons have been detected in monitor wells upgradient from the Sand Springs Petrochemical N.P.L. Site. The site being immediately upgradient and a large older manufacturing facility is suspected of being a possible source of the contamination.

SUPERFUND FILE

AUG 25 1992

REORGANIZED

M. PREPARER INFORMATION

1. NAME

Scott A. Thompson

2. TELEPHONE NUMBER

(405) 271-7168

3. DATE (mo., day, & yr.)

6/9/88